



**DETAILS AFTER REMOVAL
 FROM SUPPORTS**



**REMOVE
 PROTECTIVE COVER**

 USE A SAW TO REMOVE SUPPORTS
 FROM 3D PRINTED PARTS


1 ASSEMBLY X6










COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR	GUNZE / MR.METAL COLOR	FEDERAL STANDARD
 OLIVE DRAB	H304	C304		FS34087
 YELLOW	H4	C4		FS33538
 STAINLESS			MC213	
 FLAT BLACK	H12	C33		
 GREEN	H6	C6		
 RUSSET	H33	C81		
 GOLD			MC217	

ONLY USED WITH MK32 AD (QS MINES)
& MK 32 AD (DST MINES)

ONLY USED WITH MK32 AD (QS MINES)
& MK 32 AD (DST MINES)



MK 82 FUZING OPTIONS

M1A1	 H304/C304 MC213 H3/C4
M904	 MC213 H3/C4
USAF NOSE PLUG	 H304/C304
DSU-33	 H12/C33
OGIVE NOSE PLUG	 H33/C81
MK 32 AD (QS MINES) & MK 32 AD (DST MINES)	 MC217 MC213
FMU-113	 H12/C33