






**DETAILS AFTER REMOVAL  
FROM SUPPORTS**



 USE A SAW TO REMOVE SUPPORTS  
FROM 3D PRINTED PARTS

**1** X4





COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
OLIVE DRAB	H304	C304
STEEL	H18	C28
GRAY	H308	C308
YELLOW	H4	C4