





USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

DETAILS AFTER REMOVAL
FROM SUPPORTS



R5 X2



R6 X2



R7 X2




R8 X2




R3



R4




R1




R2


1



R6




R1




R5


2



R5




R2



R6

3



4

