





USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

DETAILS AFTER REMOVAL
FROM SUPPORTS



R3 X2



R4 X2




R5 X2




R6 X2



R7




R1




R2


1



R3




R1




R4


2



R3



R2



R4

3 X2

