



USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL FROM SUPPORTS



R5




R6



R3 X2



R4 X2




R1




R2


1 MAIN WHEELS



R4



R1



R3

2

