





USE A SAW TO REMOVE SUPPORTS  
FROM 3D PRINTED PARTS


## DETAILS AFTER REMOVAL FROM SUPPORTS



**R3 X12**



**R1 X12**



**R2 X12**



**R6 X12**




**R5 X12**



**R8 X12**




**R7 X12**




**R4 X12**

**1 X12**



**2 X12**





 [youtube.com/@reskit-usmd](https://youtube.com/@reskit-usmd)