




USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

DETAILS AFTER REMOVAL FROM SUPPORTS




R6



R9




R4 x2




R5 x2




R7




R1



R3




R2




R8

1





R7



R3



R6



R8

1 X2

