

USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


**DETAILS AFTER REMOVAL
FROM SUPPORTS**



PAINT INSTRUCTION

COLORS	GUNZE / AOEUS	GUNZE / MR.COLOR
 DARK GREEN	H64	C23
 DARK EARTH	H72	C22
 SANDY YELLOW	H79	C39

COLORS	GUNZE / AOEUS	GUNZE / MR.COLOR
 NEUTRAL GRAY	H53	C13
 FLESH	H51	C51
 DARK SEAGRAY		C22



COLORS	GUNZE / AOEUS	GUNZE / MR.METAL COLOR
 SUPER IRON		SM203

COLORS	GUNZE / AOEUS	GUNZE / MR.COLOR
 GRAY	H308	C308

COLORS	GUNZE / AOEUS	GUNZE / MR.COLOR
 METAL BLACK	H28	C78