



USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

DETAILS AFTER REMOVAL FROM SUPPORTS

R1





PAINT INSTRUCTION

COLORS	GUNZE / AQEOUS	GUNZE / MR.COLOR
STEEL	H18	C28
NEUTRAL GRAY	H53	C13
SEMI GLOSS BLACK		C92

COLORS	GUNZE / AQEOUS	GUNZE / MR.COLOR
GLOSS BLACK	H2	C2
KHAKI GREEN		C54
FLESH	H51	C51