



### DETAILS AFTER REMOVAL FROM SUPPORTS




R1




USE A SAW TO REMOVE SUPPORTS  
FROM 3D PRINTED PARTS



R2




R3



R4




R5




R6




R7




R8



R9



R10



R14




R11




R12



R13




R15




R16


1




2




3




4




5




6




7




8




9




10




11



12



STEP 12



R16

