






USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


**DETAILS AFTER REMOVAL
FROM SUPPORTS**




R3




R5




R1



R2 X4




R4 X4




R6 X4

1 X4



R4




R6


2

STEP 1


STEP 1




3



4



5



6

