


CUT



R2



R1

R3


R4

REMOVE
PROTECTIVE COVER


USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS



R7




R5



R6

1


R1



R2

2


STEP 1



R5

3

R6




R3

R4


4

STEP 2



STEP 3

5



6

