







 USE A SAW TO REMOVE SUPPORTS  
FROM 3D PRINTED PARTS




**1 LEFT SIDE**




**3** X2




**4**




5




6







**7** RIGHT SIDE



**8**







**YOU CAN FIND INSTRUCTIONS  
IN PDF FORMAT ON THE WEBSITE**

**RESKIT-MODELS.COM**

**General Issues: [info@reskit.com.ua](mailto:info@reskit.com.ua)**

**Wholesales: [sales@reskit.com.ua](mailto:sales@reskit.com.ua)**

**Claim Resolution: [claims@reskit.com.ua](mailto:claims@reskit.com.ua)**