






**DETAILS AFTER REMOVAL  
 FROM SUPPORTS**




1




2



**3**




**4**



**5**


**R24**



**STEP 4**


**6**

**R15**




**STEP 5**


7




8



9




10




**MAKE R17 SECURE ON T1 AXIS  
AND YOU CAN ROTATE R17**

**GLUE T1 TO STEP 9 ONLY**


11




12




**13**




**14**



15




16




SECURE  IN  ONE. MAKE  PART ALINE WITH   
AND THAN SECURE EVERY ONE WITH T2






17



18



# DECALS INSTRUCTION



**YOU CAN FIND INSTRUCTIONS  
IN PDF FORMAT ON THE WEBSITE**

**RESKIT-MODELS.COM**

**General Issues: [info@reskit.com.ua](mailto:info@reskit.com.ua)**

**Wholesales: [sales@reskit.com.ua](mailto:sales@reskit.com.ua)**

**Claim Resolution: [claims@reskit.com.ua](mailto:claims@reskit.com.ua)**