



USE A SAW TO REMOVE SUPPORTS FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL FROM SUPPORTS



1 X2



2 X2




YOU CAN FIND INSTRUCTIONS
IN PDF FORMAT ON THE WEBSITE

RESKIT-MODELS.COM

General Issues: info@reskit.com.ua
Wholesales: sales@reskit.com.ua
Claim Resolution: claims@reskit.com.ua

3 X2


STEP 2



R2

4

STEP 3




R4

R7

STEP 3

5


PARTS C34, C35
FROM THE KIT



CUT

6

PART FROM THE KIT



STEP 4