





USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


**DETAILS AFTER REMOVAL
FROM SUPPORTS**




1




2





3




4








7




STEP 6




8




STEP 7




9




10




11




12




13




14




15




16




17




18




19




20




21




22




23




24




25




DECAL INSTRUCTION




LEFT LANDING GEAR



RIGHT LANDING GEAR



NOSE LANDING GEAR
FRONT



NOSE LANDING GEAR
BACK

**YOU CAN FIND INSTRUCTIONS
IN PDF FORMAT ON THE WEBSITE**

RESKIT-MODELS.COM

General Issues: info@reskit.com.ua

Wholesales: sales@reskit.com.ua

Claim Resolution: claims@reskit.com.ua