





**DETAILS AFTER REMOVAL FROM SUPPORTS**




**REMOVE PROTECTIVE COVER**


 USE A SAW TO REMOVE SUPPORTS FROM 3D PRINTED PARTS



**3**



**4**



**R10 FOR F-105G (TRUMPETER 01618)  
 R9 FOR F-105D (TRUMPETER 01617)**