



COLORS	GUNZE / AOEIOUS	GUNZE / MR.COLOR
OLIVE DRAB	H304	C304
ORANGE-GLOSS		C59

USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL
FROM SUPPORTS




1




2



3



4



5

