



DETAILS AFTER REMOVAL FROM SUPPORTS




USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS




R1 x2




R6 x2



R5 x2



R2 x2






R3 x2




R4 x2


1 X2



R3




R2




R4

2 X2



3 X2



general Issues: info@reskit.com.ua / claim resolution: claims@reskit.com.ua

RESKIT-MODELS.COM

fb.com/reskit.official

instagram.com/reskit_official

youtube.com/@reskit-usmd