




**DETAILS AFTER REMOVAL FROM SUPPORTS**




**1** USE A SAW TO REMOVE SUPPORTS FROM 3D PRINTED PARTS




## PAINTING INSTRUCTION

V1




**FLAT BLACK** H12  
C33



**YELLOW** H4  
C4 + **LIGHT GULL GREY** H51  
C11


**FLAT BLACK** H12  
C33



**YELLOW** H4  
C4 + **LIGHT GULL GREY** H51  
C11

## PAINTING INSTRUCTION

V2



**WHITE** H1  
C1

COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
WHITE	H1	C1
YELLOW	H4	C4

COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
FLAT BLACK	H12	C33
LIGHT GULL GREY	H4	C4