


R1 X4



R2 X4

USE A SAW TO REMOVE SUPPORTS FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL FROM SUPPORTS




R5 X4




R6 X4



R7 X4



R8 X4




R4 X4



R3 X4

1 X4




OPTIONAL R6




DRILL AND USE A DROP OF UW-GLUE

COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR	FEDERAL STANDARD
OLIVE DRAB	H304	C304	FS 34087
YELLOW	H4	C4	FS 33538
FLAT BLACK	H12	C33	

COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR	FEDERAL STANDARD
GRAY	H308	C308	FS 36375
STEEL	H18	C28	
SILVER	H8	C8	



FUZING OPTIONS

DSU-38A/B PLGS WITH ADJUSTABLE PROXIMITY SENSOR (APS)		R4
AJ SAASM GPS ANTENNA (OPTIONAL)		R6