






USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

DETAILS AFTER REMOVAL
FROM SUPPORTS



1 X4





PAINT INSTRUCTION

COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
STEEL	H18	C28

COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
LIGHT GRAY	H338	C338