





USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


**DETAILS AFTER REMOVAL
FROM SUPPORTS**




R3 X2




R4 X2




R7 X2




R8 X2




R1



R2




R5



R6

1 MAIN WHEELS



2 FORWARD WHEELS

