






**DETAILS AFTER REMOVAL
FROM SUPPORTS**



 USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

1 X4





COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
OLIVE DRAB	H304	C304
STEEL	H18	C28
GRAY	H308	C308
YELLOW	H4	C4