






R2 X4



R3 X4



R4




R1 X4




USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL FROM SUPPORTS




R5




R6



R7





R8




R9


1 X4




R3




R1



R2



3 ONLY FOR HASEGAWA



4 ONLY FOR HASEGAWA

