



USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

DETAILS AFTER REMOVAL
FROM SUPPORTS



R2



R3




R4




R5




R1



R6




R7




R8 X2

1


FRONT WHEEL



R3



R1



R2

