







DETAILS AFTER REMOVAL FROM SUPPORTS



USE A SAW TO REMOVE SUPPORTS
 FROM 3D PRINTED PARTS

1 x4





COLOR	SGUNZE / AQUEOUS	GUNZE / MR.COLOR	FEDERAL STANDARD
GRAY	H308	C308	FS 36375
WHITE	H316	C316	FS 17875
STEEL	H18	C28	