


USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


**DETAILS AFTER REMOVAL
FROM SUPPORTS**



R2 X16



R6 X4




R5 X4

R1 X4

R4 X4

R3 X4

1 X4



R1

R2


R2

R6

R2

R2

2 X4






R5

R4

?

R3

STEP 1



COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
GRAY	H306	C306
GRAY	H308	C308
SILVER	H8	C8

12-15 ONLY FOR UKRAINIAN AIR FORCE
(WAR IN UKRAINE 2022)