










**DETAILS AFTER REMOVAL  
 FROM SUPPORTS**

 USE A SAW TO REMOVE SUPPORTS  
 FROM 3D PRINTED PARTS



**1 X4**





COLORS	GUNZE / AQEOUS	GUNZE / MR.COLOR
OLIVE DRAB	H304	C304
STEEL	H18	C28
GRAY	H308	C308
YELLOW	H4	C4