



R2 FOR P-47D 11



R3 FOR P-47D 25-26



R4 FOR P-47D 28



R5 FOR P-47D 30/P-47 M



R6 FOR P-47N



R1



USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

**DETAILS AFTER REMOVAL
FROM SUPPORTS**





YELLOW H329
C329

DARK SEAGRAY H75
C25

LEATHER C502

KHAKI GREEN H80
C54

DARK GREEN H64
C23

PAINT INSTRUCTION

COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
 DARK GREEN	H64	C23
 YELLOW	H329	C22
 DARK SEAGRAY	H75	C25

SEMI GLOSS BLACK C92

COLORS	GUNZE / AQUEOUS	GUNZE / MR.COLOR
 LEATHER		C520
 KHAKI GREEN	H51	C51
 SEMI GLOSS BLACK		C92