




USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL FROM SUPPORTS






GLUE PART R2 TO PART R3


3





4




5 X2




6





7




8






PAINT INSTRUCTION



#	COLOR	GUNZE / AQEOUS	GUNZE / MR.COLOR
A	STEEL	H18	C28
B	FLESH	H51	C51
C	TIRE BLACK		C137
D	OLIVE DRAB	H304	C304
E	KHAKI	H55	C55
F	RED BROWN	H47	C41

DECAL INSTRUCTION



08/09 - TO CHOOSE FROM

