




USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

**DETAILS AFTER REMOVAL
FROM SUPPORTS**

R2



R3




R4



R4



R1



R4



R4





PAINT INSTRUCTION

#	COLOR	GUNZE / AQEOUS	GUNZE / MR.COLOR
A	STEEL	H18	C28
B	OLIVE DRAB	H304	C304
C	KHAKI	H55	C55
D	FIELD GREEN	H340	C340
E	NAVY BLUE	H54	C14

#	COLOR	GUNZE / AQEOUS	GUNZE / MR.COLOR
F	BLUE	H5	C5
G	YELLOW	H4	C4
H	FLESH	H51	C51
I	SAIL COLOR		C45
J	HULL RED		C22