

**REMOVE
PROTECTIVE COVER**




USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

R2



R3




R4



R4



R1



R4



R4





PAINT INSTRUCTION

COLORS	GUNZE / AQEOUS	GUNZE / MR.COLOR
STEEL	H18	C28
OLIVE DRAB	H304	C304
KHAKI	H55	C55
FIELD GREEN	H340	C340
NAVY BLUE	H54	C14

COLORS	GUNZE / AQEOUS	GUNZE / MR.COLOR
BLUE	H5	C5
YELLOW	H4	C4
FLESH	H51	C51
SAIL COLOR		C45
HULL RED		C22