


USE A SAW TO REMOVE SUPPORTS
 FROM 3D PRINTED PARTS


**DETAILS AFTER REMOVAL
 FROM SUPPORTS**

1 IN ITALERI KIT INSTRUCTIONS ON PAGE 36, ON THE INNER SIDE OF THE STEP 41,
 PART 1H GRIND OFF AND POLISH


PART 1H FROM
 ITALERI KIT



2



3



4

IN ITALERI KIT INSTRUCTIONS ON PAGE 36, STEP 41, REPLACE PARTS 12F, 17PE, 6F, 41F, 48F, 11F ON STEP 4