




5 X2




USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL
FROM SUPPORTS




1 X2




2 X2




3 LEFT ENGINE



3 RIGHT ENGINE



4 X2



**USE THIS KEYHOLE FOR PROPER
R5 INSTALLATION**