




5 X2




USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL
FROM SUPPORTS




1 X2




2 X2



3 LEFT ENGINE



3 RIGHT ENGINE



4 X2

