





USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS

**DETAILS AFTER REMOVAL
FROM SUPPORTS**




R1



R2

1

CUT




**VIEW
LEFT SIDE**

**FUSELAGE
FROM THE TRUMPETER KIT**


**FUSELAGE
FROM THE TRUMPETER KIT**

CUT



**VIEW
RIGHT SIDE**

2



3

