







1 LEFT MACHINE GUN ASSEMBLY




2



3




4



5

STEP 2 AND STEP 4 ARE ATTACHED
TO STEP 3 AT THE SAME TIME,
AND THEN FASTENED TOGETHER



general Issues: info@reskit.com.ua / claim resolution: claims@reskit.com.ua


RESKIT-MODELS.COM

fb.com/reskit.official


instagram.com/reskit_official

youtube.com/@reskit-usmd

6



7 RIGHT MACHINE GUN ASSEMBLY





general Issues: info@reskit.com.ua / claim resolution: claims@reskit.com.ua

RESKIT-MODELS.COM


fb.com/reskit.official

instagram.com/reskit_official


youtube.com/@reskit-usmd





10



11



12



general Issues: info@reskit.com.ua / claim resolution: claims@reskit.com.ua


RESKIT-MODELS.COM

fb.com/reskit.official

instagram.com/reskit_official

youtube.com/@reskit-usmd

DECAL INSTRUCTION



PAINT INSTRUCTION

#	COLOR	GUNZE / AQEOUS	GUNZE / MR.COLOR
A	GRAY FS36320		SG307

#	COLOR	GUNZE / AQEOUS	GUNZE / MR.COLOR
B	METALLIC BLACK	H28	C78
C	RED	H5	C5