



CUT

 USE A SAW TO REMOVE SUPPORTS FROM 3D PRINTED PARTS




R5

R6



R2



R3




R1

R4


1 RIGHT WING



R1




R3



R6

R5




R5

R6

R5 - LOADING WEAPONS, R6 - LOADED IN PARKING POSITION

2 LEFT WING



R5 - LOADING WEAPONS, R6 - LOADED IN PARKING POSITION

LEFT VIEW

