





USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS


DETAILS AFTER REMOVAL
FROM SUPPORTS




R3 X2



R1
RIGHT



R4 X2



R2
LEFT

