




### CUT


### REMOVE PROTECTIVE COVER




USE A SAW TO REMOVE SUPPORTS  
FROM 3D PRINTED PARTS



R1




R2




R3

1



2



3

