

**DETAILS AFTER REMOVAL
FROM SUPPORTS**


 USE A SAW TO REMOVE SUPPORTS
FROM 3D PRINTED PARTS



R1



R2



R7



R4



R6



R3




R5




R8



R9



R10



R11

