






DETAILS AFTER REMOVAL FROM SPRUES





PARKING POSITION